

PRIORITY:	Installation Standard
DATE:	March 26, 2008
TITLE:	Excite Installation Best Practice Tip for Cables
ECO REFERENCE:	N/A
PRODUCT(S) AFFECTED:	All Excite signs.
SUMMARY:	This service bulletin provides a best practice tip for cable routing and installation.

Excite Installation Best Practice Tip for Cables

When connecting the cables, leave a sufficient amount of slack to create a “Service Loop”, this will allow service personnel to remove the controller and disconnect the communication cables from inside the sign. The loop also provides an alternate path for melting snow or rain (to prevent it from going straight to the connection).

